

Report of Analysis

Client:	T&A Construction Inc	Date Collected:	07/14/25 13:20
Project:	Kingsland Point Park Water Main	Date Received:	07/14/25
Client Sample ID:	END-OF-TRENCH	SDG No.:	Q2600
Lab Sample ID:	Q2600-10	Matrix:	SOIL
		% Solid:	100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Ignitability	NO		1	0	0	oC		07/15/25 14:30	1030

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits