

Initial and Continuing Calibration Verification

Client: T&A Construction Inc

SDG No.: Q2600

Project: Kingsland Point Park Water Main

RunNo.: LB136472

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV pH	pH	7.01	7	100	90-110	07/15/2025
Sample ID: CCV1 pH	pH	2.01	2.00	101	90-110	07/15/2025
Sample ID: CCV2 pH	pH	12.02	12.00	100	90-110	07/15/2025

Initial and Continuing Calibration Verification

Client: T&A Construction Inc

SDG No.: Q2600

Project: Kingsland Point Park Water Main

RunNo.: LB136498

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Cyanide	mg/L	0.094	0.099	95	90-110	07/16/2025
Sample ID: CCV1 Cyanide	mg/L	0.24	0.25	96	90-110	07/16/2025
Sample ID: CCV2 Cyanide	mg/L	0.24	0.25	96	90-110	07/16/2025
Sample ID: CCV3 Cyanide	mg/L	0.25	0.25	100	90-110	07/16/2025

Initial and Continuing Calibration Verification

Client: T&A Construction Inc

SDG No.: Q2600

Project: Kingsland Point Park Water Main

RunNo.: LB136507

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV Hexavalent Chromium	mg/L	0.497	0.5	99	90-110	07/16/2025
Sample ID: CCV1 Hexavalent Chromium	mg/L	0.492	0.5	98	90-110	07/16/2025
Sample ID: CCV2 Hexavalent Chromium	mg/L	0.495	0.5	99	90-110	07/16/2025
Sample ID: CCV3 Hexavalent Chromium	mg/L	0.497	0.5	99	90-110	07/16/2025