

Report of Analysis

| | | | | | |
|--------------------|---------------------------------|-----------|--------------------|----------------|-----------|
| Client: | T&A Construction Inc | | Date Collected: | 07/14/25 | |
| Project: | Kingsland Point Park Water Main | | Date Received: | 07/14/25 | |
| Client Sample ID: | STOCK-PILE | | SDG No.: | Q2600 | |
| Lab Sample ID: | Q2600-06 | | Matrix: | TCLP | |
| Analytical Method: | 8151A | | % Solid: | 0 | Decanted: |
| Sample Wt/Vol: | 100 | Units: mL | Final Vol: | 10000 | uL |
| Soil Aliquot Vol: | | uL | Test: | TCLP Herbicide | |
| Extraction Type: | | | Injection Volume : | | |
| GPC Factor : | 1.0 | PH : | | | |
| Prep Method : | 8151A | | | | |

| | | | | |
|-------------------|-----------|----------------|----------------|---------------|
| File ID/Qc Batch: | Dilution: | Prep Date | Date Analyzed | Prep Batch ID |
| PS031107.D | 1 | 07/16/25 10:39 | 07/17/25 20:01 | PB168886 |

| CAS Number | Parameter | Conc. | Qualifier | MDL | LOQ / CRQL | Units |
|-------------------|-------------------|-------|-----------|----------|------------|----------|
| TARGETS | | | | | | |
| 94-75-7 | 2,4-D | 9.20 | U | 9.20 | 20.0 | ug/L |
| 93-72-1 | 2,4,5-TP (Silvex) | 7.80 | U | 7.80 | 20.0 | ug/L |
| SURROGATES | | | | | | |
| 19719-28-9 | 2,4-DCAA | 733 | * | 61 - 136 | 147% | SPK: 500 |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

E = Value Exceeds Calibration Range

P = Indicates >25% difference for detected concentrations between the two GC columns

Q = indicates LCS control criteria did not meet requirements

M = MS/MSD acceptance criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

N = Presumptive Evidence of a Compound

* = Values outside of QC limits

D = Dilution

S = Indicates estimated value where valid five-point calibration was not performed prior to analyte detection in sample.

() = Laboratory InHouse Limit