284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.: Q2600 **Analytical Method:** 8151A

Client: T&A Construction Inc **DataFile :** PS031115.D

	Parameter	Spike	Sample Result	Result	Units	Rec	Rec Qual	RPD	RPD Qual	Limits Low	Limits High	Limits RPD
Lab Sample ID:	**Q2592-02MS (Column 1)**	**Client Sample ID:**		**WC-SOIL-20250711MS**								
	2,4-D	50	0	69.7	ug/L	139	*			65	135	
	2,4,5-TP(Silvex)	50	0	63.0	ug/L	126				62	139	
Lab Sample ID:	**Q2592-02MS (Column 2)**	**Client Sample ID:**		**WC-SOIL-20250711MS**								
	2,4-D	50	0	55.3	ug/L	111	*			65	135	
	2,4,5-TP(Silvex)	50	0	54.2	ug/L	108				62	139	