

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.:	<u>Q2600</u>	Analytical Method:	<u>8081B</u>
Client:	<u>T&A Construction Inc</u>	DataFile :	<u>PL096462.D</u>

	Parameter	Spike	Sample		Units	Rec	Rec		RPD		Limits	
			Result				Qual	RPD	Qual	Low	High	RPD
Lab Sample ID:	Q2592-02MS	Client Sample ID:		WC-SOIL-20250711MS								
	(Column 1)											
	gamma-BHC (Lindane)	5	0	5.00	ug/L	100				60	152	
	Heptachlor	5	0	4.90	ug/L	98				56	147	
	Heptachlor epoxide	5	0	5.30	ug/L	106				77	143	
	Endrin	5	0	5.20	ug/L	104				76	144	
	Methoxychlor	5	0	5.10	ug/L	102				70	142	
Lab Sample ID:	Q2592-02MS	Client Sample ID:		WC-SOIL-20250711MS								
	(Column 2)											
	gamma-BHC (Lindane)	5	0	5.30	ug/L	106				60	152	
	Heptachlor	5	0	5.00	ug/L	100				56	147	
	Heptachlor epoxide	5	0	5.10	ug/L	102				77	143	
	Endrin	5	0	5.00	ug/L	100				76	144	
	Methoxychlor	5	0	4.60	ug/L	92				70	142	