

LAB CHRONICLE

OrderID: Q2646
Client: Environmental Restoration, LLC
Contact: Steve Motta

OrderDate: 7/18/2025 11:47:00 AM
Project: North Arlington, NJ
Location: O11,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2646-01	FRAC TANK	Water			07/18/25 09:30			07/18/25
			Flash Point	1010B			07/21/25 14:10	
			pH	9040C			07/21/25 09:44	
			TSS	SM2540 D			07/23/25 09:30	