



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Initial and Continuing Calibration Verification

Client: Environmental Restoration, LLC

SDG No.: Q2646

Project: North Arlington, NJ

RunNo.: LB136549

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
pH		pH	7.01	7	100	90-110	07/21/2025
Sample ID:	CCV1						
pH		pH	2.01	2.00	101	90-110	07/21/2025
Sample ID:	CCV2						
pH		pH	12.02	12.00	100	90-110	07/21/2025

Initial and Continuing Calibration Verification

Client: Environmental Restoration, LLC

SDG No.: Q2646

Project: North Arlington, NJ

RunNo.: LB136561

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV						
Flash Point	o F	82.4	81	102	78-84	07/21/2025