



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,  
Fax : 908 789 8922

**Laboratory Control Sample/Laboratory Control Sample Duplicate Summary**

**SW-846**

**SDG No.:** Q2646

**Analytical Method:** 8082A

**Client:** Environmental Restoration, LLC

**Datafile :** PO112402.D

| Lab Sample ID            | Parameter | Spike | Result | Units | Rec | RPD | Qual | RPD  | Limits  |           | RPD |
|--------------------------|-----------|-------|--------|-------|-----|-----|------|------|---------|-----------|-----|
|                          |           |       |        |       |     |     |      | Qual | Low     | High      |     |
| PB168957BS<br>(Column 1) | AR1016    | 5     | 4.80   | ug/L  | 96  |     |      |      | 40 (77) | 140 (107) |     |
|                          | AR1260    | 5     | 4.20   | ug/L  | 84  |     |      |      | 40 (66) | 140 (113) |     |
| PB168957BS<br>(Column 2) | AR1016    | 5     | 4.40   | ug/L  | 88  |     |      |      | 40 (77) | 140 (107) |     |
|                          | AR1260    | 5     | 4.20   | ug/L  | 84  |     |      |      | 40 (66) | 140 (113) |     |