

LAB CHRONICLE

OrderID: Q2646
Client: Environmental Restoration, LLC
Contact: Steve Motta

OrderDate: 7/18/2025 11:47:00 AM
Project: North Arlington, NJ
Location: O11,VOA Lab

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2646-01	FRAC TANK	WATER	PCB	8082A	07/18/25	07/22/25	07/23/25	07/18/25
Q2646-03	FRAC TANK	TCLP	TCLP Herbicide	8151A	07/18/25	07/23/25	07/31/25	07/18/25