

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.:	<u>Q2646</u>	Analytical Method:	<u>8081B</u>
Client:	<u>Environmental Restoration, LLC</u>	DataFile :	<u>PL096560.D</u>

	Parameter	Spike	Sample		Units	Rec	Rec	RPD		Limits	
			Result	Result			Qual	RPD	Qual	Low	High
Lab Sample ID:	Q2641-02MS	Client Sample ID:		P001-CONCRETE001-01M							
	(Column 1)										
	gamma-BHC (Lindane)	5	0	5.60	ug/L	112				30 (60)	150 (152)
	Heptachlor	5	0	5.50	ug/L	110				30 (56)	150 (147)
	Heptachlor epoxide	5	0	5.80	ug/L	116				30 (77)	150 (143)
	Endrin	5	0	5.40	ug/L	108				30 (76)	150 (144)
	Methoxychlor	5	0.15	4.40	ug/L	87				30 (70)	150 (142)
Lab Sample ID:	Q2641-02MS	Client Sample ID:		P001-CONCRETE001-01M							
	(Column 2)										
	gamma-BHC (Lindane)	5	0	5.70	ug/L	114				30 (60)	150 (152)
	Heptachlor	5	0	5.50	ug/L	110				30 (56)	150 (147)
	Heptachlor epoxide	5	0	5.70	ug/L	114				30 (77)	150 (143)
	Endrin	5	0	5.30	ug/L	106				30 (76)	150 (144)
	Methoxychlor	5	0.14	4.50	ug/L	90				30 (70)	150 (142)