

Matrix Spike/Matrix Spike Duplicate Summary

SW-846

SDG No.:	<u>Q2646</u>	Analytical Method:	<u>8081B</u>
Client:	<u>Environmental Restoration, LLC</u>	DataFile :	<u>PL096561.D</u>

	Parameter	Spike	Sample		Units	Rec		RPD		Limits		
			Result			Rec	Qual	RPD	Qual	Low	High	RPD
Lab Sample ID:	Q2641-02MSD	Client Sample ID:		P001-CONCRETE001-01M								
	(Column 1)											
	gamma-BHC (Lindane)	5	0	5.60	ug/L	112		0		30 (60)	150 (152)	20 (20)
	Heptachlor	5	0	5.40	ug/L	108		2		30 (56)	150 (147)	20 (20)
	Heptachlor epoxide	5	0	5.70	ug/L	114		2		30 (77)	150 (143)	20 (20)
	Endrin	5	0	5.30	ug/L	106		2		30 (76)	150 (144)	20 (20)
	Methoxychlor	5	0.15	4.40	ug/L	87		0		30 (70)	150 (142)	20 (20)
Lab Sample ID:	Q2641-02MSD	Client Sample ID:		P001-CONCRETE001-01M								
	(Column 2)											
	gamma-BHC (Lindane)	5	0	5.60	ug/L	112		2		30 (60)	150 (152)	20 (20)
	Heptachlor	5	0	5.40	ug/L	108		2		30 (56)	150 (147)	20 (20)
	Heptachlor epoxide	5	0	5.60	ug/L	112		2		30 (77)	150 (143)	20 (20)
	Endrin	5	0	5.20	ug/L	104		2		30 (76)	150 (144)	20 (20)
	Methoxychlor	5	0.14	4.50	ug/L	90		0		30 (70)	150 (142)	20 (20)