

Report of Analysis

Client:	Earth Engineering Inc.	Date Collected:	07/17/25 11:30
Project:	Leon Avenue	Date Received:	07/18/25
Client Sample ID:	MH 9-8	SDG No.:	Q2651
Lab Sample ID:	Q2651-05	Matrix:	SOIL
		% Solid:	92.9

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.
Cyanide	0.044	U	1	0.044	0.26	mg/Kg	07/18/25 15:00	07/21/25 10:49	9012B

Comments: _____

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits