

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: PSEG Date Collected: 07/21/25 11:15

Project: Washington St- Bay St OP Date Received: 07/21/25

Client Sample ID: TP-2 SDG No.: Q2668
Lab Sample ID: Q2668-04 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.30	Н	1	0	0	рН		07/22/25 13:37	9045D
Ignitability	NO		1	0	0	oC		07/23/25 09:38	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	07/22/25 15:00	07/23/25 12:23	9012B
Reactive Sulfide	1.59	J	1	0.20	10.0	mg/Kg	07/22/25 15:00	07/23/25 08:53	9034

Comments: pH result reported at temperature 20.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits