

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 07/21/25 14:45

Project: Washington St- Bay St OP Date Received: 07/21/25

Client Sample ID: TP-1 SDG No.: Q2668

Lab Sample ID: Q2668-12 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	8.34	Н	1	0	0	pН		07/22/25 14:00	9045D
Ignitability	NO		1	0	0	oC		07/23/25 10:08	1030
Reactive Cyanide	0.050	U	1	0.0083	0.050	mg/Kg	07/22/25 15:00	07/23/25 11:53	9012B
Reactive Sulfide	3.19	J	1	0.20	10.0	mg/Kg	07/22/25 15:00	07/23/25 09:01	9034

Comments: pH result reported at temperature 20.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits