

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client:	Tully Environmental, Inc	Date Collected:	07/21/25
Project:	Transfer Station-SPDES	Date Received:	07/22/25
Client Sample ID:	002 35th Ave (JUNE)	SDG No.:	Q2669
Lab Sample ID:	Q2669-02	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua. DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-50-8	Copper	43.6	1	1.89	10.0	ug/L	07/22/25 12:50	07/23/25 14:06	EPA 200.7	
7439-89-6	Iron	13000	1	18.0	50.0	ug/L	07/22/25 12:50	07/23/25 14:06	EPA 200.7	
7439-92-1	Lead	41.1	1	1.21	6.00	ug/L	07/22/25 12:50	07/23/25 14:06	EPA 200.7	

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group 10

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range N = Spiked sample recovery not within control limits