

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 07/23/25 Project: Linden Generating Station - LRSA Date Received: 07/23/25 Client Sample ID: **DSN003** SDG No.: Q2683 Lab Sample ID: Q2683-07 Matrix: Water % Solid: Level (low/med): 0 low

Cas	Parameter	Conc.	Qua. I	OF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-38-2	Arsenic	10.0	U 1	2.56	10.0	ug/L	07/24/25 13:05	07/25/25 14:19	6010D	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits