

LAB CHRONICLE

OrderID:	Q2758	OrderDate:	8/1/2025 4:14:00 PM
Client:	Sciacca General Contractors, LLC	Project:	92 Clifford Street, Newark
Contact:	Rosanne Scirica	Location:	D21,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2758-02	WASTE	SOIL			08/01/25 12:00			08/01/25
			Corrosivity	9045D			08/05/25 09:10	
			Ignitability	1030			08/06/25 10:35	
			Reactive Sulfide	9034		08/05/25	08/05/25 11:30	
			Reactive Cyanide	9012B		08/04/25	08/05/25 10:33	