

Initial and Continuing Calibration Verification

Client: Sciacca General Contractors, LLC

SDG No.: Q2758

Project: 92 Clifford Street, Newark

RunNo.: LB136700

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	6.99	7	100	90-110	08/05/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	08/05/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	08/05/2025

Initial and Continuing Calibration Verification

Client: Sciacca General Contractors, LLC

SDG No.: Q2758

Project: 92 Clifford Street, Newark

RunNo.: LB136704

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.094	0.099	95	85-115	08/05/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	08/05/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	08/05/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	08/05/2025

Initial and Continuing Calibration Verification

Client: Sciacca General Contractors, LLC

SDG No.: Q2758

Project: 92 Clifford Street, Newark

RunNo.: LB136704

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
---------	-------	--------	------------	---------------	---------------------------	------------------