

## LAB CHRONICLE

|                 |                                  |                   |                            |
|-----------------|----------------------------------|-------------------|----------------------------|
| <b>OrderID:</b> | Q2758                            | <b>OrderDate:</b> | 8/1/2025 4:14:00 PM        |
| <b>Client:</b>  | Sciacca General Contractors, LLC | <b>Project:</b>   | 92 Clifford Street, Newark |
| <b>Contact:</b> | Rosanne Scirica                  | <b>Location:</b>  | D21,VOA Ref. #2 Soil       |

| LabID    | ClientID | Matrix | Test   | Method | Sample Date | Prep Date | Anal Date | Received |
|----------|----------|--------|--------|--------|-------------|-----------|-----------|----------|
| Q2758-01 | WASTE    | SOIL   |        |        | 08/01/25    |           |           | 08/01/25 |
|          |          |        | PCB    | 8082A  |             | 08/05/25  | 08/05/25  |          |
|          |          |        | TPH GC | 8015D  |             | 08/06/25  | 08/06/25  |          |