

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Aramark Uniforms Date Collected: 08/07/25 10:13 Project: Monthly 2025 Date Received: 08/07/25 Client Sample ID: **SLUDGE** SDG No.: Q2791 Lab Sample ID: Q2791-01 Matrix: SOIL % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	5.70	Н	1	0	0	pН		08/15/25 13:25	9045D
Ignitability	NO		1	0	0	oC		08/15/25 11:30	1030
Reactive Cyanide	0.0084	U	1	0.0084	0.050	mg/Kg	08/15/25 08:35	08/15/25 12:51	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	08/15/25 12:40	08/15/25 15:13	9034

Comments: pH result reported at temperature 20.6 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits