

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 08/07/25 09:37

Project: Sewaren Laydown Yard Date Received: 08/07/25

Client Sample ID: VNJ-222 SDG No.: Q2800

Lab Sample ID: Q2800-02 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.56	Н	1	0	0	pН		08/07/25 16:30	9045D
Ignitability	NO		1	0	0	oC		08/08/25 09:25	1030
Reactive Cyanide	0.013	J	1	0.0083	0.050	mg/Kg	08/11/25 10:15	08/11/25 14:02	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	08/11/25 10:15	08/11/25 12:39	9034

Comments: pH result reported at temperature 21.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits