

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 08/07/25 11:11 Project: Trenton Gas and Appliance Service MA00006789 Date Received: 08/07/25 Client Sample ID: TR-04-080725 SDG No.: Q2801 Lab Sample ID: Q2801-01 Matrix: SOIL % Solid: 95.4

Parameter	Conc.	Qua.	DF MD	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Paint Filter	1.00	U	1 1.00	1.00	ml/100gm		08/08/25 13:50	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits