

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: VERINA CONSULTING GROUP, LLC Date Collected: 08/07/25 Project: Rotor Clip NJ WTD - 2025 Date Received: 08/07/25 Client Sample ID: WATER-TREATMENT DISCHARGE SDG No.: Q2804 Lab Sample ID: Q2804-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-47-3	Chromium	69.0		1	1.06	5.00	ug/L	08/08/25 11:10	08/11/25 18:01	6010D	SW3010
7440-50-8	Copper	9.87	J	1	2.30	10.0	ug/L	08/08/25 11:10	08/11/25 18:01	6010D	SW3010
7440-02-0	Nickel	20.6		1	1.53	20.0	ug/L	08/08/25 11:10	08/11/25 18:01	6010D	SW3010
7440-66-6	Zinc	176		1	8.33	20.0	ug/L	08/08/25 11:10	08/11/25 18:01	6010D	SW3010

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group4

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference. OR = Over Range

N =Spiked sample recovery not within control limits