

 $284 \; Sheffield \; Street, \; Mountainside, \; New \; Jersey \; 07092, \; Phone \; : \; 908 \; 789 \; 8900, \\$ 

Fax: 908 789 8922

## **Report of Analysis**

Client: Ardmore Chemical Date Collected: 08/08/25 11:00 Project: Date Received: PVSC Monthly 2025 08/08/25 Client Sample ID: EFF-WASTE WATER SDG No.: Q2811 Lab Sample ID: Q2811-01 Matrix: WATER % Solid: 0

Parameter	Conc. Qu	ua.	DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Cyanide	0.0020 J	J	1 0.0012	0.0050	mg/L	08/11/25 08:10	08/11/25 12:47	SM 4500-CN C-21 plus E-21

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits