

## Report of Analysis

|                   |                           |                 |                |
|-------------------|---------------------------|-----------------|----------------|
| Client:           | Holland Manufacturing Co. | Date Collected: | 08/08/25 12:00 |
| Project:          | Pre Treatment Plant 2025  | Date Received:  | 08/08/25       |
| Client Sample ID: | AERATION                  | SDG No.:        | Q2813          |
| Lab Sample ID:    | Q2813-04                  | Matrix:         | WATER          |
|                   |                           | % Solid:        | 0              |

| Parameter | Conc. | Qua. | DF | MDL  | LOQ / CRQL | Units | Prep Date | Date Ana.      | Ana Met.     |
|-----------|-------|------|----|------|------------|-------|-----------|----------------|--------------|
| TSS       | 3330  |      | 1  | 1.00 | 4.00       | mg/L  |           | 08/11/25 10:00 | SM 2540 D-20 |

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits