

LAB CHRONICLE

OrderID: Q2819
Client: First Environment, Inc.
Contact: Al Smith

OrderDate: 8/11/2025 12:06:00 PM
Project: USACE018-44 DOD
Location: D31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2819-06	11M-S	SOIL	PCB	8082A	08/05/25	08/12/25	08/12/25	08/08/25
Q2819-11	84SB-W	SOIL	PCB	8082A	08/05/25	08/12/25	08/12/25	08/08/25
Q2819-14	17M-W	SOIL	PCB	8082A	08/05/25	08/12/25	08/12/25	08/08/25