

LAB CHRONICLE

OrderID:	Q2819	OrderDate:	8/11/2025 12:06:00 PM
Client:	First Environment, Inc.	Project:	USACE018-44 DOD
Contact:	Al Smith	Location:	D31,VOA Ref. #2 Soil

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2819-06	11M-S	SOIL			08/05/25			08/08/25
			PCB	8082A		08/12/25	08/12/25	
			Pesticide-TCL	8081B		08/12/25	08/14/25	
Q2819-06DL	11M-SDL	SOIL			08/05/25			08/08/25
			Pesticide-TCL	8081B		08/12/25	08/15/25	
Q2819-11	84SB-W	SOIL			08/05/25			08/08/25
			PCB	8082A		08/12/25	08/12/25	
			Pesticide-TCL	8081B		08/12/25	08/14/25	
Q2819-14	17M-W	SOIL			08/05/25			08/08/25
			PCB	8082A		08/12/25	08/12/25	
			Pesticide-TCL	8081B		08/12/25	08/14/25	
Q2819-14DL	17M-WDL	SOIL			08/05/25			08/08/25
			Pesticide-TCL	8081B		08/12/25	08/15/25	
Q2819-14DL 2	17M-WDL2	SOIL			08/05/25			08/08/25
			Pesticide-TCL	8081B		08/12/25	08/15/25	