

Report of Analysis

| | | | |
|-------------------|---|-----------------|----------------|
| Client: | PSEG | Date Collected: | 08/11/25 10:50 |
| Project: | Summit Gas and Appliance Service MA00006789 | Date Received: | 08/11/25 |
| Client Sample ID: | SU-04-081125 | SDG No.: | Q2823 |
| Lab Sample ID: | Q2823-01 | Matrix: | SOIL |
| | | % Solid: | 93.3 |

| Parameter | Conc. | Qua. | DF | MDL | LOQ / CRQL | Units | Prep Date | Date Ana. | Ana Met. |
|--------------|-------|------|----|------|------------|----------|-----------|----------------|----------|
| Paint Filter | 1.00 | U | 1 | 1.00 | 1.00 | ml/100gm | | 08/12/25 08:52 | 9095B |

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits