

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: G Environmental Date Collected: 08/11/25 13:30 Project: Ave B Date Received: 08/11/25 Client Sample ID: WC1 SDG No.: Q2826 Lab Sample ID: Q2826-02 Matrix: **SOIL** % Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	10.1	Н	1	0	0	pН		08/12/25 09:48	9045D
Ignitability	NO		1	0	0	oC		08/12/25 10:32	1030
Reactive Cyanide	0.013	J	1	0.0083	0.050	mg/Kg	08/13/25 08:45	08/13/25 12:45	9012B
Reactive Sulfide	3.17	J	1	0.20	10.0	mg/Kg	08/13/25 11:00	08/13/25 15:08	9034

Comments: pH result reported at temperature 21.5 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits