

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q2826

Project: Ave B

RunNo.: LB136781

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: Corrosivity	ICV	pH	7.01	7	100	90-110	08/12/2025
Sample ID: Corrosivity	CCV1	pH	2.01	2.00	101	90-110	08/12/2025
Sample ID: Corrosivity	CCV2	pH	12.02	12.00	100	90-110	08/12/2025

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q2826

Project: Ave B

RunNo.: LB136792

Analyte		Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID:	ICV						
pH		pH	7.00	7	100	90-110	08/12/2025
Sample ID:	CCV1						
pH		pH	2.01	2.00	101	90-110	08/12/2025
Sample ID:	CCV2						
pH		pH	12.02	12.00	100	90-110	08/12/2025
Sample ID:	CCV3						
pH		pH	2.01	2.00	101	90-110	08/12/2025

Initial and Continuing Calibration Verification

Client: G Environmental

SDG No.: Q2826

Project: Ave B

RunNo.: LB136800

Analyte	Units	Result	True Value	% Recovery	Acceptance Window (%R)	Analysis Date
Sample ID: ICV1 Reactive Cyanide	mg/L	0.095	0.099	96	85-115	08/13/2025
Sample ID: CCV1 Reactive Cyanide	mg/L	0.26	0.25	104	90-110	08/13/2025
Sample ID: CCV2 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	08/13/2025
Sample ID: CCV3 Reactive Cyanide	mg/L	0.25	0.25	100	90-110	08/13/2025