

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: PSEG Date Collected: 08/11/25 08:30

Project: PSEG Metro Way Date Received: 08/11/25

Client Sample ID: TP-8 SDG No.: Q2827

Lab Sample ID: Q2827-04 Matrix: SOIL

% Solid: 100

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	7.70	Н	1	0	0	pН		08/12/25 10:00	9045D
Ignitability	NO		1	0	0	oC		08/12/25 10:47	1030
Reactive Cyanide	0.012	J	1	0.0084	0.050	mg/Kg	08/13/25 08:45	08/13/25 12:45	9012B
Reactive Sulfide	6.37	J	1	0.20	10.0	mg/Kg	08/13/25 11:00	08/13/25 15:10	9034

Comments: pH result reported at temperature 22.3 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits