



284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,
Fax : 908 789 8922

Hit Summary Sheet
SW-846

SDG No.: Q2829
Client: Viva Nova Inc

Order ID: Q2829
Project ID: Metal Testing

Sample ID	Client ID	Matrix	Parameter	Concentration	C	MDL	RDL	Units
Client ID : Q2829-01	SILICA SILICA	SOIL	Silicon	213		3.47	16.9	mg/Kg



SAMPLE DATA

A

B

C

D

Report of Analysis

Client:	Viva Nova Inc	Date Collected:	08/11/25
Project:	Metal Testing	Date Received:	08/11/25
Client Sample ID:	SILICA	SDG No.:	Q2829
Lab Sample ID:	Q2829-01	Matrix:	SOIL
Level (low/med):	low	% Solid:	100

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weight)	Prep Date	Date Ana.	Ana Met.	Prep Met.
7440-21-3	Silicon	213		1	3.47	16.9	mg/Kg	08/12/25 13:05	08/13/25 16:48	6010D	SW3050

Color Before:	White	Clarity Before:	Texture:	Medium
Color After:	Yellow	Clarity After:	Artifacts:	
Comments:	Metals Group3			

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N =Spiked sample recovery not within control limits

LAB CHRONICLE

OrderID:	Q2829	OrderDate:	8/11/2025 3:00:13 PM
Client:	Viva Nova Inc	Project:	Metal Testing
Contact:	Sanjeev Goyal	Location:	D21

LabID	ClientID	Matrix	Test	Method	Sample Date	Prep Date	Anal Date	Received
Q2829-01	SILICA	SOIL	Metals Group3	6010D	08/11/25	08/12/25	08/13/25	08/11/25