

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: JACOBS Engineering Group, Inc. Date Collected: 08/12/25 11:54

Project: Former Schlumberger STC PTC Site D3868221 Date Received: 08/12/25 Client Sample ID: MW-17B-55.5-08122025DL SDG No.: Q2842

Lab Sample ID: Q2842-03DL Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	19.4	D	5	0.95	3.00	mg/L		08/13/25 16:34	9056A
Sulfate	40.6	D	5	2.30	15.0	mg/L		08/13/25 16:34	9056A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits