

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Parkway Generation Operating LLC Date Collected: 08/13/25 13:56

Project: Linden Generating Station - LRSA Date Received: 08/13/25

Client Sample ID: DSN003 SDG No.: Q2862
Lab Sample ID: Q2862-05 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
BOD5	11.4		1	0.20	2.00	mg/L		08/14/25 09:50	SM 5210 B-16
COD	29.6		1	1.50	10.0	mg/L		08/15/25 11:05	SM 5220 D-11
TSS	3.50	J	1	1.00	4.00	mg/L		08/15/25 10:00	SM 2540 D-20

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits