

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

100

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 08/13/25 13:21 Project: Lawrenceville HQ Date Received: 08/13/25 Client Sample ID: ARS10-0047 SDG No.: Q2865 Lab Sample ID: Q2865-02 Matrix: **SOIL**

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Corrosivity	6.45	Н	1	0	0	pН		08/15/25 09:35	9045D
Ignitability	NO		1	0	0	oC		08/14/25 13:37	1030
Reactive Cyanide	0.050	U	1	0.0084	0.050	mg/Kg	08/15/25 08:35	08/15/25 13:04	9012B
Reactive Sulfide	4.77	J	1	0.20	10.0	mg/Kg	08/15/25 12:40	08/15/25 15:42	9034

Comments: pH result reported at temperature 22.7 °C

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits