

Report of Analysis

Client:	JACOBS Engineering Group, Inc.	Date Collected:	08/13/25 15:00
Project:	Former Schlumberger STC PTC Site D3868221	Date Received:	08/13/25
Client Sample ID:	EB01-081325	SDG No.:	Q2869
Lab Sample ID:	Q2869-07	Matrix:	Water
		% Solid:	0

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Alkalinity	1.00	U	1	1.00	2.00	mg/L		08/15/25 08:52	SM 2320 B-21
Chloride	0.19	U	1	0.19	0.60	mg/L		08/15/25 11:59	9056A
Nitrate	0.095	U	1	0.095	0.50	mg/L		08/15/25 11:59	9056A
Sulfate	0.46	U	1	0.46	3.00	mg/L		08/15/25 11:59	9056A
TDS	1.00	U	1	1.00	10.0	mg/L		08/14/25 17:20	SM 2540 C-20

Comments:

U = Not Detected
 LOQ = Limit of Quantitation
 MDL = Method Detection Limit
 LOD = Limit of Detection
 D = Dilution
 Q = indicates LCS control criteria did not meet requirements
 H = Sample Analysis Out Of Hold Time

J = Estimated Value
 B = Analyte Found in Associated Method Blank
 * = indicates the duplicate analysis is not within control limits.
 E = Indicates the reported value is estimated because of the presence of interference.
 OR = Over Range
 N = Spiked sample recovery not within control limits