

Lab Sample ID:

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Q2878-01DL

Report of Analysis

Client: JACOBS Engineering Group, Inc. Date Collected: 08/13/25 15:45

Project: Former Schlumberger STC PTC Site D3868221 Date Received: 08/14/25

Client Sample ID: MW-18B-57.5-081325DL SDG No.: Q2878

% Solid: 0

WATER

Matrix:

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	21.4	D	10	1.90	6.00	mg/L		08/15/25 15:13	9056A
Sulfate	148	D	10	4.60	30.0	mg/L		08/15/25 15:13	9056A

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits