

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: **PSEG** Date Collected: 08/15/25 10:08 Project: Kingsland Switching Station Date Received: 08/15/25 Client Sample ID: RBR2520553 SDG No.: Q2883 Lab Sample ID: Q2883-01 Matrix: SOIL % Solid: 89.5

Parameter	Conc.	Qua.	DF M	MDL LOQ / CRQ	L Units	Prep Date	Date Ana.	Ana Met.
Paint Filter	1.00	U	1 1.	.00 1.00	ml/100gm		08/18/25 08:25	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits