

Duplicate Sample Summary

Client: Tully Environmental, Inc	SDG No.: Q2904
Project: Transfer Station-SPDES	Sample ID: Q2925-01
Client ID: OUTFALL-2MSD	Percent Solids for Spike Sample: 0

Analyte	Units	Acceptance Limit	Sample Result	Conc. Qualifier	Duplicate Result	Conc. Qualifier	Dilution Factor	RPD/ AD	Qual	Analysis Date
Oil and Grease	mg/L	+/-18	21.4		21.1		1	1.41		08/21/2025