

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Hero Construction Date Collected: 08/21/25 13:06 Project: Residential Soil Testing Date Received: 08/21/25 Client Sample ID: 27-BELL SDG No.: Q2928 Lab Sample ID: Q2928-01 Matrix: SOIL % Solid: 85.3

Parameter	Conc. Qua.	DF MDL	LOQ / CRQL	Units(Dry Weight) Prep Date	Date Ana.	Ana Met.
Cyanide	0.048 U	1 0.048	0.28	mg/Kg 08/25/25 08:05	08/25/25 15:34	9012B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits