

## Report of Analysis

|                   |                                             |                 |                |
|-------------------|---------------------------------------------|-----------------|----------------|
| Client:           | PSEG                                        | Date Collected: | 08/26/25 11:46 |
| Project:          | Summit Gas and Appliance Service MA00006789 | Date Received:  | 08/26/25       |
| Client Sample ID: | SU-03-08262025                              | SDG No.:        | Q2960          |
| Lab Sample ID:    | Q2960-01                                    | Matrix:         | SOIL           |
|                   |                                             | % Solid:        | 92.9           |

| Parameter    | Conc. | Qua. | DF | MDL  | LOQ / CRQL | Units    | Prep Date | Date Ana.      | Ana Met. |
|--------------|-------|------|----|------|------------|----------|-----------|----------------|----------|
| Paint Filter | 1.00  | U    | 1  | 1.00 | 1.00       | ml/100gm |           | 08/27/25 08:55 | 9095B    |

Comments: \_\_\_\_\_

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N = Spiked sample recovery not within control limits