

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: **PSEG** Date Collected: 08/27/25 13:36 Project: Locust Street 69kV Breaker Date Received: 08/27/25 Client Sample ID: TP4 SDG No.: Q2971 Lab Sample ID: Q2971-31 Matrix: SOIL % Solid: 88.3

Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units(Dry Weigl	nt) Prep Date	Date Ana.	Ana Met.
Cyanide	1.90		1	0.047	0.28	mg/Kg	08/28/25 08:00	08/28/25 13:44	9012B
Paint Filter	1.00	U	1	1.00	1.00	ml/100gm		08/28/25 10:27	9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits