

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Client: Safety Environmental Co. of NY, Inc. Date Collected: 08/26/25 Project: 3 Maple Drive, Roosevelt L.I NY Date Received: 08/28/25 Client Sample ID: SDG No.: Q2972 Lab Sample ID: Q2972-01 Matrix: Water % Solid: Level (low/med): low 0

Cas	Parameter	Conc.	Qua. 1	OF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-92-1	Lead	1.44	J 1	1.21	6.00	ug/L	08/28/25 14:45	08/29/25 12:32	EPA 200.7	

Color Before: Colorless Clarity Before: Clear Texture:

Color After: Colorless Clarity After: Clear Artifacts:

Comments: Metals Group3

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence

of interference.

OR = Over Range

N =Spiked sample recovery not within control limits