

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

% Solid:

91

Fax: 908 789 8922

## **Report of Analysis**

Client: Core Environmental Consultants and Services, Inc. Date Collected: 08/29/25 09:00

Project: Bayshore Soil BSM Management Date Received: 08/29/25

Client Sample ID: PAULDING-WC1 SDG No.: Q2994

Lab Sample ID: Q2994-01 Matrix: SOIL

Units Parameter Conc. DF MDL LOQ / CRQL **Prep Date** Date Ana. Ana Met. Qua. Paint Filter 09/02/25 09:00 1.00 1.00 1.00 ml/100gm9095B

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits