

## LAB CHRONICLE

|                 |                                                   |                   |                              |
|-----------------|---------------------------------------------------|-------------------|------------------------------|
| <b>OrderID:</b> | Q2994                                             | <b>OrderDate:</b> | 8/29/2025 1:47:15 PM         |
| <b>Client:</b>  | Core Environmental Consultants and Services, Inc. | <b>Project:</b>   | Bayshore Soil BSM Management |
| <b>Contact:</b> | Ronald Tramosch                                   | <b>Location:</b>  | D31,VOA Ref. #2 Soil         |

| LabID    | ClientID     | Matrix | Test         | Method | Sample Date       | Prep Date | Anal Date         | Received |
|----------|--------------|--------|--------------|--------|-------------------|-----------|-------------------|----------|
| Q2994-01 | PAULDING-WC1 | SOIL   | Paint Filter | 9095B  | 08/29/25<br>09:00 |           | 09/02/25<br>09:00 | 08/29/25 |