

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark Date Collected: 09/02/25 Project: NJ Waste Water PT Date Received: 09/04/25 Client Sample ID: WP0925-PT-SIO2-WP SDG No.: Q3016 Lab Sample ID: Q3016-07 Matrix: Water Level (low/med): % Solid: 0 low

Cas	Parameter	Conc.	Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
Dissolved	Dissolved	72100	D	5 4	400	4280	ug/L	09/23/25 09:30	09/26/25 14:53	EPA 200.	7 M200.7
Silica	Silica										

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits