

284 Sheffield Street, Mountainside, New Jersey 07092, Phone : 908 789 8900, Fax : 908 789 8922

Report of Analysis

Report of Analysis

CII.	Alliana Talaial Cara H.C. Na ad	D. (c. C. 11 (. 1.	00/02/25
Client:	Alliance Technical Group, LLC - Newark	Date Collected:	09/02/25
Project:	NJ Waste Water PT	Date Received:	09/04/25
Client Sample ID:	WP0925-PT-HG-WP	SDG No.:	Q3018
Lab Sample ID:	Q3018-07	Matrix:	Water
Level (low/med):	low	% Solid:	0

Cas	Parameter	Conc.	Qua. D	F MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	Prep Met.
7439-97-6	Mercury	24.0	D 5	0.38	1.00	ug/L	10/02/25 14:20	10/03/25 12:26	7470A	

Color Before:	Clarity Before:	Texture:
Color After:	Clarity After:	Artifacts:

Comments: Mercury

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits