

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

## **Report of Analysis**

Client: Alliance Technical Group, LLC - Newark

Project: NJ Waste Water PT Client Sample ID: WP0925-PT-DEM-WPDL

Lab Sample ID: Q3019-03DL

Date Collected: 09/02/25 10:00

Date Received: 09/04/25 SDG No.: Q3019 Matrix: WATER

% Solid: 0

Parameter	Conc. Qu	ua. DF MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.	
TOC	34.6 D	D 4 1.40	4.00	mg/L		10/07/25 14:16 SM 5310 B-14		

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

\* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits