

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark

Project: NJ Waste Water PT Client Sample ID: WP0925-PT-MIN1-WP

Lab Sample ID: Q3019-06

Date Collected: 09/02/25 10:00

Date Received: 09/04/25 SDG No.: Q3019 Matrix: WATER

% Solid: 0

Parameter	Conc. (Qua.	DF	MDL	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Bromide	5.20		1	0.37	2.00	mg/L		09/11/25 11:49	9056A
Chloride	260	OR	1	0.19	0.60	mg/L		09/11/25 11:49	9056A
Fluoride	3.40		1	0.11	0.40	mg/L		09/11/25 11:49	9056A
Sulfate	112	OR	1	0.46	3.00	mg/L		09/11/25 11:49	9056A
Sulfate	116	OR	1	0.45	5.00	mg/L		10/07/25 11:45	9038

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits