

284 Sheffield Street, Mountainside, New Jersey 07092, Phone: 908 789 8900,

Fax: 908 789 8922

Report of Analysis

Client: Alliance Technical Group, LLC - Newark

Project: NJ Waste Water PT Client Sample ID: WP0925-PT-MIN1-WPDL

Lab Sample ID: Q3019-06DL

Date Collected: 09/02/25 10:00

Date Received: 09/04/25 SDG No.: Q3019 Matrix: WATER

% Solid: 0

Parameter	Conc.	Qua.	DF MDI	LOQ / CRQL	Units	Prep Date	Date Ana.	Ana Met.
Chloride	190	OR	10 1.90	6.00	mg/L		09/11/25 13:16	9056A
Sulfate	100	D	10 4.60	30.0	mg/L		09/11/25 13:16	9056A
Sulfate	102	D	5 2.25	25.0	mg/L		10/07/25 11:48	9038

Comments:

U = Not Detected

LOQ = Limit of Quantitation

MDL = Method Detection Limit

LOD = Limit of Detection

D = Dilution

Q = indicates LCS control criteria did not meet requirements

H = Sample Analysis Out Of Hold Time

J = Estimated Value

B = Analyte Found in Associated Method Blank

* = indicates the duplicate analysis is not within control limits.

E = Indicates the reported value is estimated because of the presence of interference.

OR = Over Range

N =Spiked sample recovery not within control limits